UT203R/UT204R AC/DC Clamp Meters **User Manual**

Preface

Thank you for purchasing the new *clamp meter*. In order to use this product safely and correctly, please read this manual thoroughly, especially the *Safety Instruction* part.

After reading this manual, it is recommended to keep the manual at an easily accessible place, preferably close to the device, for future

Limited warranty and liability

Uni-Trend guarantees that the product is free from any defect in material and workmanship within one year from the purchase date. This warranty does not apply to damages caused by accident, negligence, misuse, modification, contamination and improper handling. The dealer shall not be entitled to give any other warranty on behalf of Uni-Trend. If you need warranty service within the warranty period, please contact your seller directly.

Uni-Trend will not be responsible for any special, indirect, incidental construction interest responsible to any special, indirect, incidential or subsequent damage or loss caused by using this device. As some countries or regions do not allow limitations on implied warranties and incidental or subsequent damages, the above limitation of liability may not apply to you.

1. Overview

The UT203R/UT204R are portable true RMS AC/DC clamp meters with automatic range. They are designed according to EN61010-1 CAT II 600V/CAT III 300V safety standards, and come with full-function protection which ensures users a safe and reliable measurement experience. Aside from basic measurement functions, they also have high precision current scale and high voltage frequency measurement

2. Features

- True RMS measurement Audio visual NCV electric field detection
- High voltage frequency range: 10Hz~60kHz; low voltage frequency
- High Voltage frequency range: 1012 000 k, 000 k, 000 range: range: 60Hz~10MHz UT203R AC/DC current range: 40A, 400A, frequency response:
- UT203R AC/DC current range: 40A, 400A, frequency response: 45Hz~400Hz
 UT204R AC/DC current range: 60A, 600A, frequency response: 45Hz~400Hz, live/neutral wire detection
- ACA/DCA rule interfedual with detectation for current measurement
 ACA/DCA mode memory function for current measurement
 Large capacitance (UT203R: 40mF, UT204R: 60mF) and temperature measurement (UT204R)
 Large LCD and fast refresh rate (3 times/s), capacitance measurement
- response time:
- ≤1mF: less than 3s; ≤10mF: about 6s; ≤60mF: about 8s Full-function false detecting protection for up to 600V (3.6kVA) energy surge; overvoltage and overcurrent alarm The power consumption without backlight is about 1.8 mA. The
- circuit has an automatic power saving function. The consumption in sleep state is <11uA, which effectively extends the battery life to 400 hours

Please read the safety and warning parts in this manual thoroughly.

A Caution: Please read the safety instructions carefully bef

3. Standard Accessories

Open the package and check the below items, if any is missing or damaged, please contact your supplier immediately: User manual ---------- 1 nc

--- 1 pair Test leads --K-type temperature probe ------ 1 pc (Only UT204R) Cloth bag ------ 1 pc

4. Safety Instructions

To ensure safe operation and service of the tester, follow these instructions. Failure to observe these warnings can result in severe injury or death.

The meter is designed according to EN61010-1, 61010-2-032/033 and electromagnetic radiation protection EN61326-1 safety standards, and conforms to double insulation, CAT II 600V, CAT III 300V and pollution grade II. In case the meter is not used properly as instructions e protection provided may be weakened or lost. Before each use verify tester operation by measuring a known voltage the prote

- Before use, please check if there is any item which is damaged or behaving abnormally. If any abnormal item (such as bare test lead, damaged meter casing, broken LCD, etc.) is found, or if the meter
- is considered to be malfunctioning, please do not use the meter.Do not use the meter if the rear cover or the battery cover is not covered up, or it will pose a shock hazard!
- Keep fingers behind the finger guards and away from the metal probe contacts when making measurements.
- · The function switch should be placed in the correct position before neasurement. It is forbidden to change the position during neasurement to avoid damage to the meter!
- · Do not apply voltage over 600V between any meter terminal and earth ground to prevent electric shock or damage to the meter.
 Use caution when working with voltages above AC 30Vr.m.s,
- 42Vpeak or DC 60V. Such voltages pose a shock hazard.
- Never input voltage or current which exceeds the specified limit.
 Maximum range should be selected if measured value is unknown. Before measuring resistance, diode and continuity, please disconnect all power and fully discharge all capacitors to avoid inaccuracy.

- When the " a symbol appears on the LCD, please replace the batteries in time to ensure measurement accuracy. Batteries should be removed If the meter is long-term idle.
- Do not change the internal circuit of the meter to avoid damage to the meter and user!
- Do not expose the meter in high temperature/humidity, flammable, explosive or intense magnetic environments. Clean the meter casing with a soft cloth and mild detergent. Do not use
- abrasives or solvents

5. Symbols

Symbol	Description
A	Caution, possibility of electric shock
~	Alternating current
	Direct current
	Equipment protected throughout by DOUBLE INSULATION or REINFORCED INSULATION
느	Earth (ground) TERMINAL
	Warning or Caution
Entertek 4007682	Conforms to UL STD 61010-1, 61010-2-032, 61010-2-033, Certified to CSA STD C22.2 No. 61010-1, 61010-2-032, 61010-2-033.
	It is applicable to test and measuring circuits connected

- ilar CAT II points) of the low-voltage MAINS installation.
- It is applicable to test and measuring circuits connect CAT II to the distribution part of the building's low-voltage MAINS installation

6. General Specifications

- Max LCD display counts: 4099 (UT203R), 6099 (UT204R) Polarity display: Auto Overload display: "OL" or "- OL" Low battery shutdown prompt: The "Lo.bt" interface appears on LCD and lasts for about 10s, the buzzer beeps 3 times, and the meter automatically shuts down.
- automatically shuts down. Test position error: If the source under test is not placed at the c of the clamp jaws when measuring current, ±1.0% additional error reading may be produced. Drop protection: 1m

- reading may be produced. Drop protection: 1m The maximum size of jaw opening: 28mm in diameter Battery: AAA 1.5V battery × 2 Auto power off (adjustable): The meter will auto power off if there is no operation for 15 min. Dimensions: 215mm × 63.5mm × 36mm Weight: About 235g (including batteries) Altitude: 2000m Operating temperature and humidity: 0°C~30°C (≤80%RH), 30°C~40°C (≤75%RH),40°C~50°C (≤45%RH) Storage temperature and humidity: -20°C~+60°C (≤80%RH) Electromagnetic compatibility: RF=11//m, overall accuracy=specified accuracy+5% of range: RF>11//m, no specified calculation

7. External Structure (Picture 1)

- 1) NCV sensing end
- Clamp jaws
 Hand guard
- 4) LED indicator
 5) Jaw opening trigger
- Function scale knob
- 7) LCD display
- 8) Function buttons
- 9) Signal input jack (red and positive +)
- 10)COM input jack (black and negative -)

8. Button Description SELECT Button

In composite scale, press this button to switch between the corresponding functions or ranges;

Picture 1

HOLD/BACKLIGHT Button

Short press this button to enter/exit the data hold mode, and long press (about 2s) this button to turn on/off the backlight.

MAX/MIN Button

(valid for ACV/DCV, ACA/DCA, "C/"F, resistance and capacitance scales) Short press this button to enter the maximum/minimum measurement mode and long press this button to exit.

REL Button

(valid for ACV/DCV, DCA, "C/"F and capacitance scales).


Press this button to store the current reading as a reference for future readings. When the LCD display value is reset to zero, the stored reading will be subtracted from the future readings. Press this button again to exit the relative value mode

9.Operating Instructions

- 9.1 AC/DC Current Measurement (Picture 2) Select the corresponding current range.
- Press the trigger to open the clamp jaws, and fully enclose one conductor.
 Only one conductor can be measured at a time, or the measurement reading will be wrong.
- A Caution:
- Do not insert the testing leads during current measurement to avoid electric shock

LINI-T


- The current measurement must be taken with safeguard protection Press the REL button to return to zero before the DC current measurement, and meanwhile the center hole of jaw should be
- perpendicular to the current direction to ensure accuracy. The open circuit zeroing reading may be relatively large after (high)
 Dc current measurement. Please perform theAC current detection
 - again to counteract the remanence signal by alternating electric field.



- 9.2 AC/DC Voltage and Voltage Frequency (% duty cycle) Measurement (Picture 3)
- Select the corresponding function scale
- Insert the red test lead into the "positive" jack, and the black into the "COM" jack.
- Connect test leads with both ends of the measured objects

A Caution

- Do not input voltage above 600V to prevent electric shock or damage The input impedance of each range scale is $10M\Omega$, this load effect
- in high resistance measurement may cause error. If the input impedance is lower than $10k\Omega$, the error can be ignored ($\leq 0.1\%$).
- Be cautious to avoid electric shock when measuring high voltage Please check the functions by applying a known voltage before use he functions by applying a known voltage before use.



9.3 Continuity Test/Resistance/Diode/Capacitance

Connect test leads with both ends of the measured object.

Caution:
Do not input voltage above DC 60V or AC 30V to avoid personal

Please disconnect all the other parts of the circuit to avoid inaccuracy.

Before the resistance online measurement, please do disconnect all the power and fully discharge all capacitors to avoid injury or

• If the resistance is over 0.5Ω when the test leads are short-circuited,

If the measured resistor is open or the resistance exceeds the maximum range, the LCD will display "OL". Measured value = displayed value – probe short circuit value

It is recommended to use "REL" measurement mode for capacitance

Picture 4

(UT204R only)

Insert K-type thermocouple to the meter fix the temperature probe

9.4 Temperature Measurement (UT202R only, Picture 5)

on the measured object, and read after the value is stable

Picture 5

Select the temperature measurement function scale

*

Diode

Κ

please check the test leads for looseness or other abnormalities

Measurement (Picture 4) Select the corresponding function scale. Insert the red test lead into the "V+ $C \Omega$ +Hz " jack, and the black into the "COM" jack.

device damage.

less than 100nF

9.5 NCV AC Electric Field Sensing (Picture 6a)

The electric field sensing sensitivity is divided into two levels The electric field sensing sensitivity is divided into two levels ("EFHI" and "EFLo"). The meter defaults to "EFHI". Users can select different sensitivity levels according to the intensity of the measured electric field. Select "EFHI" of NCV when electric field is around 220V AC 50Hz/B0Hz. Bring the NCV sensing end close to a charged electric field (socket, insulated wire, etc.). The LCD will display the segment ¹¹ with begins and red LED flashing As the intensity of the segment electric field increases, the more segments (----) display, the higher frequency of buzzer beeps and LED flashins. Select "EFLo" when the electric field is around 110V AC 50Hz/60Hz.

▲ Caution: Use the NCV sensing end to approach measured electric field, otherwise the measurement sensitivity will be affected. When the measured electric field voltage is over 100VAC, observe whether the conductor is insulated to avoid personal injury.



Picture 6a

9.6 Others

Auto power off: The meter will automatically power off to save power if there is no operation for 15 min. You can wake it up by pressing any button or restart it after turning the switch to OFF.
Press and hold the SELECT button in off state and then turn on the

- Press and hold the SELECI button in off state and then turn on the meter again to disable the auto power off function. Restart the meter after shut it down to resume this function. Buzzer: When any button is pressed or the function switch is turned, if it is valid, the buzzer will make one beep (about 0.25s). The buzzer will also beep intermittently to indicate the over range during the voltage or current measurement.
- Voltage of current measurement.
 Low battery detection: The battery voltage will be automatically detected as long as the meter is on. If it is lower than 2.6V, the LCD will display the "□" symbol.
 Low battery shutdown function: When the battery voltage is lower than 2.5V, the LCD displays the "□" symbol, the "Lo.bt" interface appears and lasts for about 10s, the buzzer makes consecutive base as a linear out then the meter automation when the use (not seen as the second when the second se beeps 3 times, and then the meter automatically shuts down (no interface is displayed).

10.Probe usage

TESTING IN CAT III MEASUREMENT LOCATIONS Ensure the test lead shield pressed firmly in place. Failure to use the CAT III shield increases arc-flash risk.



TESTING IN CAT II MEASUREMENT LOCATIONS CAT III shields may be removed for CAT II locations. This will a CAT III shields may be removed for CAT II loca testing on recessed conductors such as standa Take care not to lose the shields. all outle



11. Technical Specifications

Accuracy: ± (%reading + counts), the calibration period is 1 year Ambient temperature and humidity: $23^{\circ}C\pm 5^{\circ}C$; $\leq 80\%$ RH. Temperature coefficient: the accuracy assured temperature condition is $18^{\circ}C-28^{\circ}C$, the range of ambient temperature fluctuation is stable within $\pm 1^{\circ}C$. When the temperature is less than $18^{\circ}C$ or over $28^{\circ}C$, the additional temperature coefficient error is 0.1 x (specified accuracy)/°C.

10.1 Current Measurement AC Current

Rai	nge	Resolution	Accuracy
UT203R	UT204R	Resolution	Accuracy
40.00A	60.00A	0.01 A	± (2%+5)
400.0A	600.0A	0.1 A	± (2 /0+3)

DC Current

Ran	ige	Resolution	Accuracy
UT203R	UT204R	Resolution	Accuracy
40.00A	60.00A	0.01 A	± (2%+5)
400.0A	600.0A	0.1 A	± (2 /0+3)

Caution:

- Accuracy guarantee range: 5%~100% of range When the measured current reaches the warnir
- ing value, there
- will be an alarm sound (UT203R: 410A, UT204R: 610A) With DC current DCA mode, LCD may display non-zero value in open circuit state, users can press "REL" button to clear display to zero before each measurement.

10.2 Voltage Measurement


DC Voltage

Range		Resolution	Accuracy	
UT203R	UT204R	Resolution	roourdoy	
400.0mV	600.0mV	0.1mV	± (0.7 +3	
4.000V	6.000V	0.001V		
40.00V	60.00V	0.01V	± (0.5 +2	
400.0V	600.0V	0.1V	± (0.5 +2	
600V		1V		

AC Voltage/Voltage Frequency				
Range		Resolution	Accuracy	
UT203R	UT204R	Resolution	Accuracy	
4.000V	6.000V	0.001V	± (1.0 +5	
40.00V	60.00V	0.01V		
400.0V	600.0V	0.1V	± (0.8 +5	
600V		1V		
Voltage Frequency 10Hz~60KHz		0.01Hz~0.01kHz	± (0. 5%+2)	

- Caution:
 UT203R: short press "SELECT" in AC voltage/Hz scale to enter the Hz function;
 UT204R: long press "SELECT" to enter/exit the Hz function, the input
- The input impedance is about 10MO Current/voltage frequency response: 45Hz ~ 400Hz, displays true RMS
- value
- value Accuracy guarantee range: 1%~100% AC crest factor of non-sinusoidal wave can reach 3.0 at 4000 counts while can only reach 1.8 at 6000 counts, the additional error should be added for the corresponding crest factor as follows: A. Add 3% when the peak factor is $1 \sim 2$ B. Add 5% when the peak factor is $2 \sim 2.5$ C. Add 7% when the peak factor is 2.5 ~ 3 ould be

10.3 Continuity/Diode Measureme



10.4 Resistance Measurement

	· · · · · · · · · · · · · · · · · · ·		
Range		Resolution	Accuracy
UT203R	UT204R	Resolution	roourdoy
400.0Ω	600.0Ω	0.1Ω	± (1.0 +2
4.000kΩ	6.000kΩ	0.001KΩ	
40.00kΩ	60.00kΩ	0.01KΩ	± (0.8 +2
400.0kΩ	600.0kΩ	0.1KΩ	
4.000ΜΩ	6.000MΩ	0.001MΩ	± (2,5%+5)
40.00MΩ	60.00MΩ	0.01MΩ	- (2. 3/0+3)

Caution:

- Measured resistance value = displayed value resistance value of short circuited test leads
- Open circuit voltage is about 1V
- Overload protection: 600Vrms

10.5 Capacitance Measurement

Range		Resolution	Accuracy
UT203R	UT204R	Resolution	Accuracy
40.00nF	60.00nF	0.01nF	
400.0nF	600.0nF	0.1nF	
4.000uF	6.000uF	0.001µF	± (4%+5)
40.00uF	60.00uF	0.01µF	± (4/0+3)
400.0uF	600.0uF	0.1µF	
4.000mF	6.000mF	0.001mF	±10%
40.00mF	60.00mF	0.01mF	± 10%

A Caution

· Measured value = displayed value - open circuit value of the test leads (For capacitance ≤100nF. "REL" mode is recommended, open circuit

has residual reading). The guaranteed accuracy is 1%~100%

Overload protection: 600Vrms

10.6 Frequency Measurement

10Hz~10MHz 0.01Hz~0.01MHz ±	(0. 1%+4)

Caution: Measurement sensitivity:

≤100kHz: 200mVrms≤ input range≤30Vrms;

>100kHz~1MHz: 600mVrms≤ input range≤30Vrms; >1MHz~10MHz: 1Vrms≤ input range≤30Vrms

Duty ratio is only applicable to \leq 10kHz square wave measurement with a range of 1Vp-p: If frequency≤1kHz, duty cycle will be 10.0%-95.0% If frequency>1kHz, duty cycle will be 30.0%-70.0%


10.8 Temperature Measurement (UT204R only)

Range	Resolution	Accuracy
-40°C~40°C		±4°C
40°C~500°C	1°C	± (1.5%+5)
500°C~1000°C		± (2.0%+5)
-40°F~104°F		±6°F
104°F~932°F	1°F	± (2.0%+6)
932°F~1832°F		± (2.5%+4)

A Caution:

The meter displays "OL" after startup, it is only suitable for K-type thermocouple (Nickel-Chromium ~ Nickel-Silicon temperature sensor) and temperature measurements below 1000°C/1832°F. The formula for Celsius to Fahrenheit is °F =1.8°C + 32.

10.9 NCV



11. Maintenance

A Warning: Before opening the rear cover of meter , remove test leads to avoid electric shock.

11.1 General Maintenance


- Clean the meter casing with a soft cloth and mild detergent. Do not use abrasives or solvents!
- Do not use the tester or test leads if they appear to have any abnormality.
 The maintenance and service must be implemented by qualified
- professionals or designated departments

11.2 Battery Replacement (Picture 7)

When the " \square " symbol appears on the LCD, please replace the batteries in time to ensure measurement accuracy. Batteries specification 2 standard AAA 1.5V batteries

Operation

- Turn off the meter and remove the test leads from the input terminals.
- Unscrew the screw of the battery compartment, remove the battery cover, and take out the used batteries as shown.
 Replace the 2 standard AAA batteries according to the polarity indication.



UNI-T.

UNI-TREND TECHNOLOGY (CHINA) CO., LTD. UNI-TREND TECHNOLOGY (C No.6, Gong Ve Bei 1st Road, Songshan Lake National High-Tech Industrial Development Zone, Dongguan City, Guangdong Province, China Tet: (86-769) 8572 3888 www.uni-tend.com Made in China 50900

